


Installation Instructions

Surface Fixed



Cadenza
Page 1 of 3



Instrument Components:

-  x4
M8 Nyloc Nut
-  x2
M6x20 Security Screw
-  x4
2 Part Cover Cap
-  x1
M6 Saddle Strap

Metric
Conversion:
250mm/ 10"
300mm/ 12"
450mm/ 18"
850mm/ 33"
1.5m/ 59"



Weight of heaviest part **7kg** (Cadenza) SD
Weight of heaviest part **13kg** (Cadenza) HD

1. Attach the steel legs to the base of the instrument with the M8 Nyloc Nuts and 2 part security caps. **(1.1)** (See Assembly Guide)



2. Attach Surface Fixing posts to legs **(1.2)** (See Ground Fix Post Installation Sheet)

3. **Locate Plate** in desired location and mark holes to fix to desired surface.

4. Fix to Surface using recommended ground anchors not supplied

5. Make sure all fixings are covered and secure using cover caps provided

6. Attach the 1 pair of beater to the saddle strap on the leg. **(1.3)**



Pair Small Red
Beaters X1

Surface Fix
Components:

-  x1
-  x1
-  x4

**Ground Anchors
not supplied**

Spares available from
percussionplay.com or from your
local distributor

18 - 24Kg




Assembly Guide PPCADE

Tools:



x1 TX 30 Driver Bit
x1 TX 40 Driver Bit

COMPONENTS LIST:

-  2 Part Cover Cap X4
-  M8 Nyloc nut X4
-  Saddle Strap X1
-  M6x20 Pin torx X2
-  M10x70 Pin torx X2
-  M10 Barrel Nut Pin torx X2




Thread Lock Solution
Required (Not Supplied)



PPCADE FRONT



PPCADE SIDE



Surface Fixed

Cadenza
Page 2 of 3



Instrument Components:

- x4 M8 Nyloc Nut
- x2 M6x20 Security Screw
- x4 2 Part Cover
- x1 Cap
- M6 Saddle Strap

Thread Lock Solution
Required (Not Supplied)



Pair Small Red
Beaters X1

Surface Fix Components:

- x1 M10x70 Security Screw
- x1 M10 Barrel Nut
- x4 2 Part Cover Cap

Ground Anchors
not supplied

Spares available from
percussionplay.com or from your
local distributor

18 -24Kg

Tools:

 x2
 TX 45 Driver Bit

Surface Fixed

Cadenza
Page 3 of 3



Components:



x1

M10 Barrel Nut



x1

M10x70 Security Screw




x4


2 Part Cover Cap

Thread Lock Solution
 Required (Not Supplied)


Metric
 Conversion:
 50mm/ 2"
 250mm/ 10"
 350mm/ 14"
 400mm/ 16"
 450mm/ 18"



Locate the Surface fix
 Plate into the leg of the
 instrument.



Fix instrument to Surface
 fix plate using M10 bolt
 and Barrel Nut and use
thread locking solution
 to prevent fixings working
 loose.



Fix Surface Plate to the
 ground surface **Ground
 Anchors Not provided**
 cover fixings with caps
 provided

Repeat Parts 1-3 for both legs